

## TCR<sup>®</sup> Thin Film Embedded Resistor Foil Etching Process Recommendations Using Cupric Chloride for Nickel Chromium (NiCr) Resistive Material

# TECHNICAL BULLETIN

Nickel chromium resistive material can be selectively removed with various chemistries to give a clean, well defined resistor. Most circuit fabricators use acid etchants, most commonly cupric chloride, for primary image and resistive layer width definition. A second etch step to define the resistor length requires a different chemistry to ensure copper removal without resistive layer etch or degradation. The nickel chromium resistive material layer will exhibit a matte grey finish after defining the resistor image. The processing can be properly controlled provided attention is paid to several considerations.

#### What to Consider

The first consideration is ensuring proper chemistries for the resistor defining processing. A solution made up of commercially available cupric chloride and hydrochloric acid is recommended for copper and nickel chromium during resistor width definition. The chemistry removes the copper and minimizes the amount of undercut of the copper and nickel chromium.

The second consideration is the proper chemistries for selective copper removal to define resistor length. A solution made up of commercially available ammoniacal etchant is the preferred chemistry for this process. The ammoniacal chemistry selectively etches the copper leaving the resistive layer intact.

The last consideration is the method of application of the etching chemistry. The removal of the copper and nickel chromium can be performed in either a spray chamber or dip tank. The spray chamber method is preferred to better control etch rates and circuit definition. The temperature and dwell time in the chemistry is solution dependent.

#### **Conclusions**

The copper and nickel chromium components can be completely removed with excellent circuit definition when care is taken to follow the considerations.

Other chemistries are known etchants of copper and nickel chromium. When using other chemistries to remove copper and Nickel Chromium other than recommended above, consult the Ticer Technologies Technical Marketing or Research and Development.


Ticer Technologies, providing innovative products and quality services to printed circuit board fabricators and laminators worldwide.

### Copper and Nickel Chromium Resistive Material Removal Chemistry and Processing Parameters

Etch 1 Solution Copper & Nickel Chromium removal Resistor Width definition	200 g/l CuCl <sub>2</sub> 60g/l HCl
Temperature:	120° F (52° C)
Method:	Spray chamber or dip tank
Time:	Adjust for proper etching of copper weight
Etch 2 Solution	267g/I NH <sub>4</sub> CI
Selective Copper removal	1 g/l ortho-phosphoric acid
Resistor length definition	392 ml NH₄OH
	10 g/l CuCl <sub>2</sub>
Temperature:	130 - 140º F (54 - 60º C)
Method:	Spray chamber or dip tank
Time:	Adjust for proper etching of copper weight

The information in this process guideline is intended to assist you in processing Ticer Technologies embedded passive materials. It is not intended to and does not create any warranties expresses or implied, including any warranty of merchantability or fitness for a particular application. The user should determine suitability of Ticer Technologies materials for each application.

## Etching Sequence of Nickel Chromium (NiCr) Resistive Materials



The information in this process guideline is intended to assist you in processing Ticer Technologies embedded passive materials. It is not intended to and does not create any warranties expresses or implied, including any warranty of merchantability or fitness for a particular application. The user should determine suitability of Ticer Technologies materials for each application.

> TICER Technologies service mark is owned by Ticer Technologies, L.L.C., Chandler, AZ. TCR is a registered trademark owned by Nippon Mining & Metals Co., Ltd., Tokyo, Japan. Revised 02/09 Technical Bulletin #05-0004 © 2006 Ticer Technologies